

GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report

District: 2
Bridge Inspector: Vince Tanner
Location ID: 181-00069X-001.42W
Structure ID: 181-5008-0

Inspection Date: 12/11/2012
Over: DOZIER BRANCH
County: Lincoln
Road Name: JONES MARTIN ROAD

Inspection Area: 02

Skew: 00

Span #:	1
Length:	25.0

Upstream -

Upstream +		1	2
02/17/1997	SGM/JTB		10.00
12/03/1998	JTB/RMS		9.00
12/07/2000	JTB\RMS		9.00
12/10/2002	JTB/VTT		9.40
12/01/2004	JTB/VTT		9.40
12/07/2006	JTB/VTT		8.90
12/29/2008	JTB/VTT		9.20
12/15/2010	VTT/BRL		9.20
12/11/2012	VTT/BRL		10.80

Downstream -

Downstream +		1	2
02/17/1997	SGM/JTB		6.00
12/03/1998	JTB/RMS		7.20
12/07/2000	JTB\RMS		7.20
12/10/2002	JTB/VTT		7.20

GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report

District: 2
Bridge Inspector: Vince Tanner
Location ID: 181-00069X-001.42W
Structure ID: 181-5008-0

Inspection Date: 12/11/2012
Over: DOZIER BRANCH
County: Lincoln
Road Name: JONES MARTIN ROAD

Inspection Area: 02

Skew: 00

		1	2
12/01/2004	JTB/VTT		7.20
12/07/2006	JTB/VTT		6.20
12/29/2008	JTB/VTT		7.20
12/15/2010	VTT/BRL		7.20
12/11/2012	VTT/BRL		7.10


GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report


District: 2
 Bridge Inspector: Vince Tanner
 Location ID: 181-00069X-001.42W
 Structure ID: 181-5008-0

Inspection Date: 12/11/2012
 Over: DOZIER BRANCH
 County: Lincoln
 Road Name: JONES MARTIN ROAD

Inspection Area: 02
 Skew: 00



- A: 7
- B: 2
- C: 5
- D: 10
- E: 1.9
- F: 16
- G: 9
- H: 1
- I: 4
- J: 1
- K: 2



Location of Bridge Height 11' rear of abutment 2

Scour Condition: 7 Waterway Adequacy: 8 Channel Protection: 6

Comments:

0 = SubStructure
 15 = Channel Skew

 15 = Stream Angle