

GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report

District: 2
Bridge Inspector: Vince Tanner
Location ID: 009-00092X-002.12N
Structure ID: 009-5011-0

Inspection Date: 3/14/2012
Over: FISHING CREEK
County: Baldwin
Road Name: ROBERTS ROAD

Inspection Area: 02

Skew: 00

Span #:	1
Length:	40.0

Upstream -

Upstream +		1	2
03/25/1998	SGM/JTB		9.70
03/02/2000	JTB/RMS		9.70
03/06/2002	JTB/VTT		9.50
03/08/2004	JTB/VTT		9.50
03/08/2006	JTB/VTT		9.50
03/31/2008	JTB/VTT		9.70
03/25/2010	VTT/BRL		9.70
03/14/2012	VTT/BRL		9.70

Downstream -

Downstream +		1	2
03/25/1998	SGM/JTB		8.80
03/02/2000	JTB/RMS		9.80
03/06/2002	JTB/VTT		9.50
03/08/2004	JTB/VTT		9.50
03/08/2006	JTB/VTT		9.50

GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report

District: 2
Bridge Inspector: Vince Tanner
Location ID: 009-00092X-002.12N
Structure ID: 009-5011-0

Inspection Date: 3/14/2012
Over: FISHING CREEK
County: Baldwin
Road Name: ROBERTS ROAD

Inspection Area: 02

Skew: 00

		1	2
03/31/2008	JTB/VTT		9.40
03/25/2010	VTT/BRL		9.40
03/14/2012	VTT/BRL		9.40

GEORGIA DEPARTMENT OF TRANSPORTATION


Waterway Report

District: 2
 Bridge Inspector: Vince Tanner
 Location ID: 009-00092X-002.12N
 Structure ID: 009-5011-0


Inspection Date: 3/14/2012
 Over: FISHING CREEK
 County: Baldwin
 Road Name: ROBERTS ROAD

Inspection Area: 02

Skew: 00



- A: 8
- B: 1
- C: 1
- D: 09.0
- E: 01.1
- F: 38
- G: 10
- H: 1
- I: 1
- J: 1
- K: 2



Location of Bridge Height 10' rear of abutment 2

Scour Condition: 8 Waterway Adequacy: 7 Channel Protection: 7

Comments:

0 = SubStructure
 0 = Channel Skew
 0 = Stream Angle