

GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report

District: 2
Bridge Inspector: JW Matthews
Location ID: 033-01290F-010.21E
Structure ID: 033-0040-0

Inspection Date: 6/21/2012
Over: WALNUT BRANCH
County: Burke
Road Name: QUAKER ROAD

Inspection Area: 10

Skew: 00

| | | | |
|----------------|------|------|------|
| Span #: | 1 | 2 | 3 |
| Length: | 15.0 | 15.0 | 15.0 |

Upstream -

| Upstream + | | 1 | 2 | 3 | 4 |
|------------|---------|---|-------|-------|------|
| 09/20/2000 | WSS,WCS | | 8.00 | 11.00 | 3.00 |
| 02/02/2005 | RMO SWS | | 9.70 | 10.00 | 2.00 |
| 06/20/2006 | JWM CB | | 9.00 | 10.00 | 3.00 |
| 07/16/2008 | JWM CB | | 9.50 | 10.50 | 3.00 |
| 06/25/2010 | JWM LCR | | 11.00 | 9.80 | 3.00 |
| 06/21/2012 | JWM-JRH | | 10.30 | 10.00 | 2.70 |

Downstream -

| Downstream + | | 1 | 2 | 3 | 4 |
|--------------|---------|---|-------|-------|------|
| 09/20/2000 | WSS,WCS | | 9.00 | 14.00 | 3.00 |
| 02/02/2005 | RMO SWS | | 10.60 | 13.40 | 3.00 |
| 06/20/2006 | JWM CB | | 9.00 | 13.00 | 3.00 |
| 07/16/2008 | JWM CB | | 9.00 | 12.50 | 3.00 |
| 06/25/2010 | JWM LCR | | 10.30 | 12.30 | 3.00 |
| 06/21/2012 | JWM-JRH | | 10.00 | 12.00 | 3.00 |


GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report


District: 2
 Bridge Inspector: JW Matthews
 Location ID: 033-01290F-010.21E
 Structure ID: 033-0040-0

Inspection Date: 6/21/2012
 Over: WALNUT BRANCH
 County: Burke
 Road Name: QUAKER ROAD

Inspection Area: 10
 Skew: 00



- A: 8
- B: 0
- C: 14
- D: 09.2
- E: 02.8
- F: 17
- G: 8
- H: 0
- I: 14
- J: 1
- K: 4



Location of Bridge Height 2' rear Bent 3

Scour Condition: 6 Waterway Adequacy: 8 Channel Protection: 5

Comments:

0 = SubStructure
 0 = Channel Skew
 0 = Stream Angle