

# GEORGIA DEPARTMENT OF TRANSPORTATION

## Waterway Report

**District:** 6  
**Bridge Inspector:** Willie Reid  
**Location ID:** 045-00838F-002.08N  
**Structure ID:** 045-0074-0

**Inspection Date:** 6/12/2012  
**Over:** BECKMILL CREEK  
**County:** Carroll  
**Road Name:** TYUS VEAL ROAD

**Inspection Area:** 09

**Skew:** 00

<b>Span #:</b>	1	2
<b>Length:</b>	<b>24.0</b>	<b>24.0</b>

Upstream -

Upstream +		1	2	3
09/22/1998	JMC		15.80	11.70
06/28/2000	JMC/WBR		14.70	10.90
07/25/2002	JMC/WBR		14.70	10.90
07/22/2004	JMC-WBR		14.80	10.90
08/07/2006	JMC-WBR		14.30	10.90
09/10/2008	JMC-WBR		14.50	10.90
07/12/2010	WBR/TDT		14.80	11.50
06/12/2012	WBR/JEM		14.60	11.20

Downstream -

Downstream +		1	2	3
09/22/1998	JMC		14.60	13.80
06/28/2000	JMC/WBR		14.90	10.80
07/25/2002	JMC/WBR		14.90	10.80
07/22/2004	JMC-WBR		14.70	10.80
08/07/2006	JMC-WBR		14.00	11.30

# GEORGIA DEPARTMENT OF TRANSPORTATION

## Waterway Report

**District:** 6  
**Bridge Inspector:** Willie Reid  
**Location ID:** 045-00838F-002.08N  
**Structure ID:** 045-0074-0

**Inspection Date:** 6/12/2012  
**Over:** BECKMILL CREEK  
**County:** Carroll  
**Road Name:** TYUS VEAL ROAD

**Inspection Area:** 09  
**Skew:** 00

---

		1	2	3
09/10/2008	JMC-WBR		14.30	11.30
07/12/2010	WBR/TDT		14.50	11.40
06/12/2012	WBR/JEM		14.10	11.40

**GEORGIA DEPARTMENT OF TRANSPORTATION**


*Waterway Report*

District: 6  
 Bridge Inspector: Willie Reid  
 Location ID: 045-00838F-002.08N  
 Structure ID: 045-0074-0


Inspection Date: 6/12/2012  
 Over: BECKMILL CREEK  
 County: Carroll  
 Road Name: TYUS VEAL ROAD

Inspection Area: 09

Skew: 00



- A: 12
- B: 0
- C: 12
- D: 13.7
- E: 01.8
- F: 14
- G: 12
- H: 0
- I: 22
- J: 1
- K: 3



Location of Bridge Height 4' rear of bent #2

Scour Condition: 5      Waterway Adequacy: 9      Channel Protection: 8

**Comments:**

No comments are required.

0 = SubStructure

0 = Channel Skew

0 = Stream Angle