

GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report

District: 6
Bridge Inspector: Danny Mealer
Location ID: 055-00019X-000.03S
Structure ID: 055-5011-0

Inspection Date: 4/9/2012
Over: CHATTOOGA RIVER TRIB
County: Chattooga
Road Name: GREEN ROAD

Inspection Area: 06

Skew: 00

Span #:	1
Length:	26.0

Upstream -

Upstream +		1	2
04/03/1998	BDH KW		2.40
03/17/2000	BDH DEM		2.50
03/27/2002	DEM HWB		2.50
03/29/2004	DEM HWB		2.50
03/23/2006	DEM HWB		2.90
05/14/2008	DEM AW		2.90
04/14/2010	DEM HWB		2.70
04/09/2012	DEM HWB		2.90

Downstream -

Downstream +		1	2
04/03/1998	BDH KW		3.70
03/17/2000	BDH DEM		3.50
03/27/2002	DEM HWB		3.60
03/29/2004	DEM HWB		3.60
03/23/2006	DEM HWB		3.60

GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report

District: 6
Bridge Inspector: Danny Mealer
Location ID: 055-00019X-000.03S
Structure ID: 055-5011-0

Inspection Date: 4/9/2012
Over: CHATTOOGA RIVER TRIB
County: Chattooga
Road Name: GREEN ROAD

Inspection Area: 06
Skew: 00

		1	2
05/14/2008	DEM AW		6.00
04/14/2010	DEM HWB		3.70
04/09/2012	DEM HWB		4.20


GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report


District: 6
 Bridge Inspector: Danny Mealer
 Location ID: 055-00019X-000.03S
 Structure ID: 055-5011-0

Inspection Date: 4/9/2012
 Over: CHATTOOGA RIVER TRIB
 County: Chattooga
 Road Name: GREEN ROAD

Inspection Area: 06
 Skew: 00



- A: 0
- B: 0
- C: 0
- D: 06.0
- E: 01.0
- F: 20
- G: 0
- H: 0
- I: 6
- J: 1
- K: 2



Location of Bridge Height + 9' from abutment #1

Scour Condition: 7 Waterway Adequacy: 9 Channel Protection: 5

Comments:

0 = SubStructure
 0 = Channel Skew
 0 = Stream Angle