

GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report

District: 4
Bridge Inspector: Billy NeSmith
Location ID: 071-00565F-000.90E
Structure ID: 071-0050-0

Inspection Date: 1/16/2013
Over: OKAPILCO CREEK
County: Colquitt
Road Name: DOERUN-NORMAN PARK

Inspection Area: 04

Skew: 00

Span #:	1	2	3	4
Length:	39.0	39.0	39.0	39.0

Upstream -

Upstream +		1	2	3	4	5
04/03/1997	LRJ		13.00	11.00	12.00	3.00
03/02/1999	LEM		14.10	11.10	11.00	4.00
02/01/2001	RAC		13.50	12.00	12.00	3.00
02/05/2003	BCN		13.30	10.60	11.20	3.80
01/18/2005	BCN		11.80	9.40	10.60	2.50
01/23/2007	BCN		12.90	10.20	11.40	3.60
02/05/2009	TWL		12.30	10.10	10.90	3.50
01/27/2011	BCN		12.50	10.00	10.80	3.50
01/16/2013	TWL		12.70	10.20	10.70	3.50

Downstream -

Downstream +		1	2	3	4	5
04/03/1997	LRJ		10.00	13.00	11.00	3.00
03/02/1999	LEM		9.00	14.00	11.00	4.00
02/01/2001	RAC		8.00	14.00	11.00	3.00
02/05/2003	BCN		8.50	12.00	11.00	3.00

GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report

District: 4
Bridge Inspector: Billy NeSmith
Location ID: 071-00565F-000.90E
Structure ID: 071-0050-0

Inspection Date: 1/16/2013
Over: OKAPILCO CREEK
County: Colquitt
Road Name: DOERUN-NORMAN PARK

Inspection Area: 04

Skew: 00

		1	2	3	4	5
01/18/2005	BCN		7.00	10.60	9.30	2.50
01/23/2007	BCN		7.40	13.00	10.60	3.80
02/05/2009	TWL		7.50	12.00	10.10	3.50
01/27/2011	BCN		6.70	12.70	10.60	3.90
01/16/2013	TWL		6.80	13.20	10.40	3.80


GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report


District: 4
 Bridge Inspector: Billy NeSmith
 Location ID: 071-00565F-000.90E
 Structure ID: 071-0050-0

Inspection Date: 1/16/2013
 Over: OKAPILCO CREEK
 County: Colquitt
 Road Name: DOERUN-NORMAN PARK

Inspection Area: 04
 Skew: 00



- A: 9
- B: 18
- C: 20
- D: 11.0
- E: 02.2
- F: 117
- G: 8
- H: 12
- I: 19
- J: 1
- K: 5



Location of Bridge Height BENT 3

Scour Condition: 7 Waterway Adequacy: 8 Channel Protection: 7

Comments:

None.

0 = SubStructure
 45 = Channel Skew
 45 = Stream Angle