

GEORGIA DEPARTMENT OF TRANSPORTATION

Bridge Component Report

District: 4
Bridge Inspector: Billy NeSmith
Location ID: 071-00565F-000.90E
Structure ID: 071-0050-0

Inspection Date: 1/16/2013
Over: OKAPILCO CREEK
County: Colquitt
Road Name: DOERUN-NORMAN PARK

Inspection Area: 04

SubStructure Data

Bent#	Type	Foundation	Col	#Cols	Piling	#Piles	Sway	CAP	Remarks
1	A	DP		0		0		C	Foundation Concealed.
2	B	SF	C	2		0		C	
3	B	SF	C	2		0		C	
4	B	SF	C	2		0		C	
5	A	DP		0		0		C	Foundation Concealed.

SuperStructure Data

Span#	Beam Type	Spacing	Length	#Beams	Remarks
1	Concrete "T" Beam	6.80	39.00	4	18"W x 22"H & 18"W x 23"H
2	Concrete "T" Beam	6.80	39.00	4	18"W x 22"H & 18"W x 23"H
3	Concrete "T" Beam	6.80	39.00	4	18"W x 22"H & 18"W x 23"H
4	Concrete "T" Beam	6.80	39.00	4	18"W x 22"H & 18"W x 23"H

Bearing Data

Span#	Rear Type Bearing	FWD Type Bearing	Remarks
1	08 - Beam on Cap	08 - Beam on Cap	
2	08 - Beam on Cap	08 - Beam on Cap	
3	08 - Beam on Cap	08 - Beam on Cap	
4	08 - Beam on Cap	08 - Beam on Cap	