

# GEORGIA DEPARTMENT OF TRANSPORTATION

## Bridge Component Report

**District:** 3  
**Bridge Inspector:** Keith Pinckard  
**Location ID:** 093-00054X-000.60E  
**Structure ID:** 093-5006-0

**Inspection Date:** 7/2/2013  
**Over:** LILLY BRANCH  
**County:** Dooly  
**Road Name:** WEEKS ROAD

**Inspection Area:** 08

### SubStructure Data

Bent#	Type	Foundation	Col	#Cols	Piling	#Piles	Sway	CAP	Remarks
1	A	ZZ		0		0		C	
2	B	DP		0	T	6		C	
3	B	DP		0	T	9		C	Has crutch bents.
4	B	DP		0	T	8		C	Has crutch bents.
5	B	DP		0	T	8		C	Has crutch bents.
6	B	DP		0	T	7		C	Has crutch bents.
7	B	DP		0	T	6		C	
8	A	ZZ		0		0		C	

### SuperStructure Data

Span#	Beam Type	Spacing	Length	#Beams	Remarks
1	Steel	4.00	16.00	7	W12x31
2	Steel	4.00	16.00	7	W12x31
3	Steel	4.00	16.00	7	W12x31
4	Steel	4.00	16.00	7	W12x31
5	Steel	4.00	16.00	7	W12x31
6	Steel	4.00	16.00	7	W12x31
7	Steel	4.00	16.00	7	W12x31

### Bearing Data

Span#	Rear Type Bearing	FWD Type Bearing	Remarks
1	08 - Beam on Cap	08 - Beam on Cap	
2	08 - Beam on Cap	08 - Beam on Cap	
3	08 - Beam on Cap	08 - Beam on Cap	
4	08 - Beam on Cap	08 - Beam on Cap	
5	08 - Beam on Cap	08 - Beam on Cap	
6	08 - Beam on Cap	08 - Beam on Cap	

# GEORGIA DEPARTMENT OF TRANSPORTATION

## Bridge Component Report

**District:** 3  
**Bridge Inspector:** Keith Pinckard  
**Location ID:** 093-00054X-000.60E  
**Structure ID:** 093-5006-0

**Inspection Date:** 7/2/2013  
**Over:** LILLY BRANCH  
**County:** Dooly  
**Road Name:** WEEKS ROAD

**Inspection Area:** 08

---

7      08 - Beam on Cap      08 - Beam on Cap