

# GEORGIA DEPARTMENT OF TRANSPORTATION

## Bridge Component Report

**District:** 2  
**Bridge Inspector:** Vince Tanner  
**Location ID:** 181-00069X-001.42W  
**Structure ID:** 181-5008-0

**Inspection Date:** 12/11/2012  
**Over:** DOZIER BRANCH  
**County:** Lincoln  
**Road Name:** JONES MARTIN ROAD

**Inspection Area:** 02

---

### SubStructure Data

Bent#	Type	Foundation	Col	#Cols	Piling	#Piles	Sway	CAP	Remarks
1	A		C	1		0		C	Concrete Wall
2	A		C	1		0		C	Concrete Wall

---

### SuperStructure Data

Span#	Beam Type	Spacing	Length	#Beams	Remarks
1	Steel	5.30	25.00	5	S12 x 31.8 - Double beams

---

### Bearing Data

Span#	Rear Type Bearing	FWD Type Bearing	Remarks
1	08 - Beam on Cap	08 - Beam on Cap	

---