

GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report

District: 6
Bridge Inspector: Willie Reid
Location ID: 233-00380X-000.11S
Structure ID: 233-5040-0

Inspection Date: 12/5/2011
Over: LITTLE CEDAR CREEK
County: Polk
Road Name: MOUNTAIN HOME LOOP ROAD

Inspection Area: 09

Skew: 00

Span #:	1
Length:	27.0

Upstream -

Upstream +		1	2
01/29/1998	JMC		7.30
12/13/1999	JMC-WBR		7.10
01/07/2002	JMC-WBR		7.10
12/16/2003	JMC-WBR		7.50
11/17/2005	JMC/WBR		7.50
12/05/2007	JMC-WBR		7.30
12/15/2009	WBR/OAO		7.70
12/05/2011	WBR/TDT		7.50

Downstream -

Downstream +		1	2
01/29/1998	JMC		6.90
12/13/1999	JMC-WBR		7.90
01/07/2002	JMC-WBR		7.90
12/16/2003	JMC-WBR		6.90
11/17/2005	JMC/WBR		6.90

GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report

District: 6
Bridge Inspector: Willie Reid
Location ID: 233-00380X-000.11S
Structure ID: 233-5040-0

Inspection Date: 12/5/2011
Over: LITTLE CEDAR CREEK
County: Polk
Road Name: MOUNTAIN HOME LOOP ROAD

Inspection Area: 09

Skew: 00

		1	2
12/05/2007	JMC-WBR		6.90
12/15/2009	WBR/OAO		7.10
12/05/2011	WBR/TDT		7.60

GEORGIA DEPARTMENT OF TRANSPORTATION


Waterway Report

District: 6
 Bridge Inspector: Willie Reid
 Location ID: 233-00380X-000.11S
 Structure ID: 233-5040-0


Inspection Date: 12/5/2011
 Over: LITTLE CEDAR CREEK
 County: Polk
 Road Name: MOUNTAIN HOME LOOP ROAD

Inspection Area: 09

Skew: 00



- A: 6
- B: 0
- C: 0
- D: 06.0
- E: 03.0
- F: 27
- G: 6
- H: 0
- I: 0
- J: 1
- K: 2



Location of Bridge Height 9.0' Forward Of Abutment #1.

Scour Condition: 5 Waterway Adequacy: 7 Channel Protection: 6

Comments:

No comments are required at this time.

0 = SubStructure
 0 = Channel Skew
 0 = Stream Angle