

# GEORGIA DEPARTMENT OF TRANSPORTATION

## Waterway Report

**District:** 3  
**Bridge Inspector:** Bryon Patterson  
**Location ID:** 255-02082F-010.10N  
**Structure ID:** 255-0039-0

**Inspection Date:** 8/30/2012  
**Over:** HEADS CREEK  
**County:** Spalding  
**Road Name:** VAUGHN ROAD

**Inspection Area:** 03

**Skew:** 00

<b>Span #:</b>	1	2	3	4	5	6
<b>Length:</b>	20.0	20.0	20.0	20.0	20.0	20.0

Upstream -

Upstream +		1	2	3	4	5	6	7
10/18/2000	JAA/AW		3.30	13.20	12.80	12.00	4.80	1.00
10/17/2002	BDH/JTE		4.60	13.00	13.60	12.20	5.70	1.40
09/22/2004	WBP/JTE		5.20	14.30	12.50	12.70	5.70	1.90
09/15/2006	WBP/JTE		4.70	15.00	15.30	13.80	5.70	1.60
09/25/2008	WBP/		4.80	15.20	15.80	14.00	6.00	2.40
09/02/2010	WBP/		5.30	15.00	14.40	13.50	6.40	2.00
08/30/2012	WBP/MOG		4.60	14.80	14.20	13.40	5.60	1.80

Downstream -

Downstream +		1	2	3	4	5	6	7
10/18/2000	JAA/AW		3.00	10.80	11.90	9.90	4.00	1.00
10/17/2002	BDH/JTE		3.80	10.90	12.60	10.00	4.60	0.90
09/22/2004	WBP/JTE		4.80	11.70	10.80	10.50	5.30	1.60
09/15/2006	WBP/JTE		4.70	12.70	14.00	12.00	5.30	1.00
09/25/2008	WBP/		4.90	13.10	14.00	12.10	6.30	1.70
09/02/2010	WBP/		4.50	12.60	12.80	11.70	6.20	1.50

# GEORGIA DEPARTMENT OF TRANSPORTATION

## Waterway Report

**District:** 3  
**Bridge Inspector:** Bryon Patterson  
**Location ID:** 255-02082F-010.10N  
**Structure ID:** 255-0039-0

**Inspection Date:** 8/30/2012  
**Over:** HEADS CREEK  
**County:** Spalding  
**Road Name:** VAUGHN ROAD

**Inspection Area:** 03  
**Skew:** 00

---

		1	2	3	4	5	6	7
08/30/2012	WBP/MOG		4.30	12.50	12.50	11.60	6.50	1.50

# GEORGIA DEPARTMENT OF TRANSPORTATION


## Waterway Report

District: 3  
 Bridge Inspector: Bryon Patterson  
 Location ID: 255-02082F-010.10N  
 Structure ID: 255-0039-0


Inspection Date: 8/30/2012  
 Over: HEADS CREEK  
 County: Spalding  
 Road Name: VAUGHN ROAD

Inspection Area: 03

Skew: 00



- A: 9
- B: 0
- C: 6
- D: 11.9
- E: 03.3
- F: 52
- G: 8
- H: 15
- I: 22
- J: 2
- K: 6



Location of Bridge Height    5' forward of bent 3 (up)

Scour Condition:        6        Waterway Adequacy:    6        Channel Protection:    7

Comments:

0 = SubStructure  
 0 = Channel Skew  
 0 = Stream Angle