

GEORGIA DEPARTMENT OF TRANSPORTATION

Bridge Component Report

District: 3
Bridge Inspector: Bryon Patterson
Location ID: 255-02082F-010.10N
Structure ID: 255-0039-0

Inspection Date: 8/30/2012
Over: HEADS CREEK
County: Spalding
Road Name: VAUGHN ROAD

Inspection Area: 03

SubStructure Data

Bent#	Type	Foundation	Col	#Cols	Piling	#Piles	Sway	CAP	Remarks
1	A			0		0		C	
3	B	DP		0	T	8	X	C	
2	B	DP		0	T	9		C	
5	B	DP		0	T	10		C	
6	B	DP		0	T	8		C	
7	A			0		0		C	
4	B	DP		0	T	7	X	C	

SuperStructure Data

Span#	Beam Type	Spacing	Length	#Beams	Remarks
1	Concrete	4.00	20.00	8	12" deck panels
2	Concrete	4.00	20.00	8	12" deck panels
3	Concrete	4.00	20.00	8	12" deck panels
4	Concrete	4.00	20.00	8	12" deck panels
5	Concrete	4.00	20.00	8	12" deck panels
6	Concrete	4.00	20.00	8	12" deck panels

Bearing Data

Span#	Rear Type Bearing	FWD Type Bearing	Remarks
1	08 - Beam on Cap	08 - Beam on Cap	felt paper
2	08 - Beam on Cap	08 - Beam on Cap	felt paper
3	08 - Beam on Cap	08 - Beam on Cap	felt paper
4	08 - Beam on Cap	08 - Beam on Cap	felt paper
5	08 - Beam on Cap	08 - Beam on Cap	felt paper
6	08 - Beam on Cap	08 - Beam on Cap	felt paper