

GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report

District: 2
Bridge Inspector: Vince Tanner
Location ID: 301-00062X-002.75E
Structure ID: 301-5012-0

Inspection Date: 1/31/2013
Over: LONG CREEK
County: Warren
Road Name: ANSLEY ROAD

Inspection Area: 02

Skew: 00

Span #:	1	2	3
Length:	33.0	33.0	33.0

Upstream -

Upstream +		1	2	3	4
03/25/1997	SGM/JTB		10.00	14.00	3.00
04/19/1999	JTB/RMS		10.10	14.50	3.30
02/06/2001	JTB		12.40	14.00	3.30
01/23/2003	JTB/VTT		11.20	14.00	3.30
02/01/2005	JTB/VTT		11.20	14.30	3.30
02/14/2007	JTB/VTT		11.20	14.30	3.30
02/11/2009	JTB/VTT		11.70	16.50	3.30
02/03/2011	VTT/BRL		12.30	14.60	3.30
01/31/2013	VTT/BRL		12.00	14.80	3.60

Downstream -

Downstream +		1	2	3	4
03/25/1997	SGM/JTB		10.00	14.00	4.00
04/19/1999	JTB/RMS		10.10	14.40	3.60
02/06/2001	JTB		10.00	13.70	3.60
01/23/2003	JTB/VTT		10.00	13.70	3.60

GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report

District: 2
Bridge Inspector: Vince Tanner
Location ID: 301-00062X-002.75E
Structure ID: 301-5012-0

Inspection Date: 1/31/2013
Over: LONG CREEK
County: Warren
Road Name: ANSLEY ROAD

Inspection Area: 02

Skew: 00

		1	2	3	4
02/01/2005	JTB/VTT		10.00	14.60	3.60
02/14/2007	JTB/VTT		10.00	13.00	3.60
02/11/2009	JTB/VTT		10.00	14.00	3.60
02/03/2011	VTT/BRL		10.20	13.70	3.60
01/31/2013	VTT/BRL		10.30	13.60	3.30


GEORGIA DEPARTMENT OF TRANSPORTATION

Waterway Report


District: 2
 Bridge Inspector: Vince Tanner
 Location ID: 301-00062X-002.75E
 Structure ID: 301-5012-0

Inspection Date: 1/31/2013
 Over: LONG CREEK
 County: Warren
 Road Name: ANSLEY ROAD

Inspection Area: 02
 Skew: 00



- A: 12
- B: 2
- C: 5
- D: 13.7
- E: 1.1
- F: 29
- G: 11
- H: 28
- I: 32
- J: 2
- K: 4



Location of Bridge Height 2' rear of bent 3

Scour Condition: 7 Waterway Adequacy: 8 Channel Protection: 7

Comments:

0 = SubStructure
 15 = Channel Skew

 15 = Stream Angle